





Highlights H2002 Hawker 800XP N300CQ S/N 258555

- 4,119 Hours
- Engines enrolled on MSP Gold
- WiFi
- ASD-B
- E-F-G + 96 months inspections completed in 2018
- Excellent Condition





Airframe

4,129 Hours - 2,491 Cycles

Engines

Honeywell TFE731-5BR-1H 4,119 Hours – 2,491 Cycles Enrolled on MSP Gold

APU:

Honeywell GTCP36-150W - 2,894 Hours

Features

- Jeppesen Electronic Charts
- Dee Howard Thrust Reversers
- Honeywell N1 Digital Electronic Engine Controls
- ADS-B Out Version 2 Compliant
- Aircell ATG 2000 with Gogo Talk & Text and 3G Wi-Fi
- Garmin GXM30 XM Weather Antenna/Receiver with Wiring Provisions for Garmin aera 796
- Hawker Beechcraft Supplemental Type Certificate for use of Michelin NBT Main Gear Tires
- Honeywell DL-950 USB Data Loader
- LoPresti Boom Beam Wing Taxi & Landing Light Kit
- Devore Tail Logo Lights
- 3rd Long Range Oxygen Bottle

Avionics

- √ 3-Tube EFIS
- ✓ Collins FMS 3000 w/GPS-4000A
- ✓ EFIS: Dual Honeywell EDZ-817 with MFD
- ✓ AUTOPILOT: Honeywell DFZ-8000
- ✓ FMS: Dual Honeywell NZ-2000 (with dual GPS & software 6.1)
- ✓ TCAS: Honeywell TCAS 2000 (TCAS II)
- ✓ EGPWS: Honeywell Mk VII (with windshear detection)
- ✓ RADAR: Honeywell Primus 880 (with LSZ-860 Lightning Sensor)
- ✓ RMU: Dual Honeywell RM-855 (LCD)
- ✓ NAV: Dual Honeywell RNZ-850
- ✓ COM: Dual Honeywell RCZ-833 (with 8.33 kHz spacing)
- ✓ HF: Dual BendixKing KHF-950 with Coltech SELCAL
- ✓ AFIS: Honeywell VHF
- ✓ CVR: Universal CVR-30B
- ✓ ELT: Artex C406-1




	Λ Ι	I A I	$\overline{}$
$\mathbf{\nu}$	ΔΙ	ш	
	\neg	ΗN	

Matterhorn White with accent stripes of Team Blue and Titanium HT.

INTERIOR:

8-passenger configuration: club grouping of 4 individual chairs in the forward area, a 3-place divan opposite a single chair located further aft. An observer's jump seat in stowed in LH cockpit closet. The galley/refreshment center is located adjacent to the entry door and includes a coffee maker and a microwave oven. The private lavatory is situated rear of the passenger seating area. The passenger entertainment system includes an Airshow 400 map system, DVD player, a LCD monitor in RH forward cabin bulkhead, and 3G WiFi. The passenger seats are upholstered in "Pecan" colored leather. The divan is upholstered in beige fabric. The aircraft passenger chair seat cushions, observer's jump seat, and lavatory seat have been fire blocked to meet the requirements of FAR Part 25.853(c).




































+(1) 561-691-3545

Info@ThePrivateJetCompany.com