

1997 Dassault SN 35

Falcon 2000



Kevin O'Leary, Ph.D.

koleary@jetadvisors.com

+1.781.999.4618



www.jetadvisors.com

1997 Falcon 2000 SN 35 N623HD

Aircraft Listing Details:

Total Hours: **8,616**

Total Landings: **5,110**

Engines: Model: CFE738-1-1B

Hours:	7,519	8,195
--------	--------------	--------------

Cycles:	4,509	4,868
---------	--------------	--------------

Program:	CSP
----------	------------

APU: Honeywell GTCP36-150

Hours:	4,203
--------	--------------

Cycles:	6,678
---------	--------------

Program:	Honeywell MSP
----------	----------------------

AIRCRAFT HIGHLIGHTS:

- Proline 21 Upgrade With Synthetic Vision
- 3 Owners Since New
- GOGO AVANCE L5
- Dry Bay Mod
- 2015 P&I by WestStar Aviation
- Enrolled on CASP
- WAAS
- Super Sound Proofing
- ADS-B Out
- FDR

Avionics:

COLLINS PROLINE 21

EFIS: COLLINS EFIS-4000 (4-TUBE)

COMM: DUAL COLLINS VHF-422D

NAV: DUAL COLLINS VIR-432

DME: DUAL COLLINS DME-442

ADF: DUAL COLLINS ADF-462

RADAR: COLLINS TWR-850

X/PDR: DUAL COLLINS TDR-94D MODE S w/ ENHANCED FLIGHT ID

AUTOPILOT: COLLINS APS-4000

HF: KING KHF-950

FMS: DUAL COLLINS FMS-6100

GPS: DUAL COLLINS GPS-4000S

IRS: DUAL HONEYWELL LASEREF III

R/ALT: COLLINS ALT-55B

Specifications Must Be Verified By Buyer



www.jetadvisors.com

200 Hanscom Drive, Suite 301 Bedford, MA 01730

+1.781.999.4618

Kevin O'Leary, Ph.D.

koleary@jetadvisors.com

Interior:

Completed by WestStar Aviation 2015

PAX: Executive/10

Seating: Taupe leather seats, forward 4-place club, two aft club seats opposite aft 4-place dining group, crew jumpseat

Carpet: Beige & gray

Refreshment: Microwave

Business: GOGO L5 Avance

Exterior:

Completed by WestStar Aviation 2015

Maintenance Status:

Gear overhauled March 2021

2C check completed by WestStar March 2021

Unscheduled Repairs:

4/10/2022 - WestStar Aviation
Ramp Rash repaired
Hole in Radome, Fuselage Dent

3/28/2019 - Dallas Aeronautical Services
Nose Cone repaired

Specifications Must Be Verified By Buyer

1997 Falcon 2000 SN 35 N623HD



Specifications Must Be Verified By Buyer

1997 Falcon 2000 SN 35 N623HD



Specifications Must Be Verified By Buyer

1997 Falcon 2000 SN 35 N623HD



Specifications Must Be Verified By Buyer



Specifications Must Be Verified By Buyer

1997 Falcon 2000 SN 35 N623HD



Specifications Must Be Verified By Buyer

1997 Falcon 2000 SN 35 N623HD



Specifications Must Be Verified By Buyer

1997 Falcon 2000 SN 35 N623HD



Specifications Must Be Verified By Buyer

1997 Falcon 2000 SN 35 N623HD



Specifications Must Be Verified By Buyer

1997 Falcon 2000 SN 35 N623HD



Specifications Must Be Verified By Buyer

1997 Falcon 2000 SN 35 N623HD



Specifications Must Be Verified By Buyer

1997 Falcon 2000 SN 35 N623HD



Specifications Must Be Verified By Buyer

 **JETADVISORS**®
www.jetadvisors.com

200 Hanscom Drive, Suite 301 Bedford, MA 01730
+1.781.999.4618

Kevin O'Leary, Ph.D.
koleary@jetadvisors.com



Jet Advisors is an independent company with years of experience in the private jet industry. Our team has been involved in over 500 jet transactions and we have the expertise to assist you with your private jet needs.

We combine our experience in the industry with up-to-date information from our industry experts to provide you with the insightful, detailed information needed to make the right decision for an acquisition or sale of a private jet or if you are considering committing to a private jet charter company.

Jet Advisors will assist you in every step of the process.

**SERVING CUSTOMERS
AROUND THE GLOBE**

Talk to Us www.jetadvisors.com **+1.781.999.4618**

Connect with Us **LINKEDIN** **FACEBOOK** **TWITTER**

Specifications Must Be Verified By Buyer



200 Hanscom Drive, Suite 301 Bedford, MA 01730
+1.781.999.4618

Kevin O'Leary, Ph.D.
koleary@jetadvisors.com